



ISSN 0975-413X  
CODEN (USA): PCHHAX

Der Pharma Chemica, 2020, 12(4): 17-20  
(<http://www.derpharmachemica.com/archive.html>)

## Comparative Characterisation of Ground and Surface Water Contamination by Anthropogenic Activities

Krishnaveni J<sup>1\*</sup>, Kamalakannan N<sup>2</sup>, Ramapandi K<sup>3</sup>, Vanavan M<sup>3</sup> and Prakash Kumar R<sup>3</sup>

<sup>1</sup>Faculty of Chemistry, Suguna College of Engineering, Coimbatore, Tamilnadu, India

<sup>2</sup>Faculty of Civil Engineering, Suguna College of Engineering, Coimbatore, Tamilnadu, India

<sup>3</sup>Department of Civil Engineering, Suguna College of Engineering, Coimbatore, Tamilnadu, India

\*Corresponding author: Krishnaveni J, Faculty of Chemistry, Suguna College of Engineering, Coimbatore, Tamilnadu, India, E-mail: [venijosh73@gmail.com](mailto:venijosh73@gmail.com)

---

### ABSTRACT

Ground and surface water samples have been collected from the local area tanks. Totally 16 samples were collected and the chemical characteristics of the sample has been studied namely pH, Electric conductivity, Total Dissolved Solids, Total Hardness, Chloride, Alkalinity and Fluoride. These tested parameters are compared with BIS standard parameters, so that the level of anthropogenic agents was identified. Semi structured interview was conducted and the impact of the pollution on the human health has been assessed.

**Keywords:** Electric conductivity, Titration method, Anthropogenic activities

---

### INTRODUCTION

Waste disposal has always been an important issue for human societies. Solid wastes are disposed on or below the land surface resulting in potential sources of ground water contamination. Coimbatore city is one of the rapidly developing cities in Tamil nadu which needs some definite waste disposal management techniques in order to maintain the ecosystem.

The survey works done by the investigators pertaining to the topic, their findings and recommendations are reviewed. Barde, et al. (2014) examined that waste disposal facilities are mainly responsible for the gradual quality degradation of subsurface fresh water reservoirs [1]. Balachandar, et al (2010) examined that the problem of water quality has become more important than quantity, as the environmental problems are becoming more serious in different parts of the world due to the intervention of human activities [2]. Jin-zhu, et al. (2002) addressed the effect of the population growth, development of industrial and agricultural production and the petroleum exploitation, brought about the unceasing expansion of artificial oasis and abrupt increase of water demand [3]. Ei-Hames et al (2011) examined one of the critical problems that hinder the sustainable development in developing countries located in arid zones [4]. The suitability of ground water for domestic use was determined on the basis of pH, TH, and TDS and by comparing them with the Bureau of Indian Standards (BIS) requirements [5]. Patel and Chaudhari (2014) examined that ground water is an important source of water supply for municipalities, agriculture, and industry [6]. Coimbatore district in western part of Tamilnadu, which lies between 10013'N and 11023' N latitudes 76039'E and 77030E longitudes. It covers a total geographical area of 7,649 km<sup>2</sup>.

### METHODOLOGY

The methodology comprises of data collection, and assessment of sociological consequences.

### pH metry and Electric conductivity

pH and Electric conductivity for all the collected samples were measured using pH meter and conductivity meter. pH value of all the collected samples are well within the permissible limit. Effect of high and low concentration of pH and the treatment required to decrease the pH is Tables 1 & 2. Electrical conductivity for all the collected samples was measured using conductivity meter. Electrical conductivity values for most of the sample are above the permissible limits.

### Total Dissolved Solids

TDS value for some of the samples is exceeding the permissible limits. Tables 1&2 shows the possible sources for high TDS, effects of high TDS and the treatment required for reducing TDS.

### Total hardness

The total hardness is measured by titration method. EDTA is taken as burette solution, 20 ml of collected sample is taken in a conical flask and two drops of EBT is added as indicator, color change from red to blue. The burette reading is noted down to precede the calculation of total hardness. Sources, effects and treatment methods for reducing hardness are shown in Table.

### Alkalinity

The presence of carbonates, bicarbonates, and hydroxides are the main cause of alkalinity in nature water. Titration method is used to measure alkalinity. The calculated alkalinity values of both surface and groundwater samples of all the four tanks are compared to BIS values of Tables 1 & 2.

### Chloride

The permissible limit for chloride is 250 mg/l to 1000 mg/l. The calculated chloride values of surface and ground water samples were compared with the BIS values of Tables 1 & 2 shown the source, effects and treatment measures to reduce the concentration of chloride.

### Fluoride

Fluoride ions maybe present either naturally or artificially in drinking water and are absorbed to the some degree in the bone structure of the body and the tooth enamel. Fluoride ions at extremely high level may cause dislocation of teeth. Permissible limit of fluoride ions is 0.6 mg/l-1.5 mg/l for ground water. All the collected samples are well below the desirable limits. Fluoride at lower concentration causes some beneficial effects on teeth [7]. Tables 1 & 2 shows the sources for presence of fluoride in water, effects of high concentration of fluoride on human, treatment required to reduce the concentration of fluoride [8] (Figures 1-7).

## RESULTS AND DISCUSSION

**Table 1:** Effect of Chemical Characteristics of Ground Water Samples

SAMPLE	pH	EC	HARDNESS	TDS	CHLORIDE	ALKALINITY	FLOURIDE
C.B.S.1	7.69	2.0	1650	400	538.0	850	0.51
C.B.S.2	7.54	2.2	1700	250	538.8	800	0.23
UK.S.1	6.50	2.1	2200	210	452.7	250	0.43
UK.S.2	6.51	2.0	1950	280	457.2	260	0.20
S.P.S.1	7.05	1.9	1900	180	396.1	400	1.83
S.P.S.2	7.01	2.0	1850	240	395.2	490	1.49
S.N.S.1	7.07	2.0	1900	110	376.5	1900	0.58
S.N.S.2	7.05	2.2	1990	155	375.7	1850	0.91

C.B.S = COIMBATORE BIG TANK(SULUR)


UK. S = UKKADAM

S.P.S = SAMALAPURAM


S.N.S = SINGANALLUR

**Table 2:** Effect of Chemical Characteristics of Surface Water Sample

Sample	pH	EC	HARDNESS	TDS	CHLORIDE	ALKALINITY	FLOURIDE
C.B.S.1	7.35	1.2	1875	380	585.5	700	0.44
C.B.S.2	7.36	1.3	2025	430	586.6	725	0.32
UK.S.1	5.70	1.1	1925	300	426.1	525	0.24
UK.S.2	5.80	1.3	1750	290	428.9	550	0.23
S.P.S.1	8.44	1.7	2000	190	420.0	350	0.46
S.P.S.2	8.10	1.6	1700	320	416.5	400	1.18
S.N.S.1	6.32	1.7	1950	265	105.0	600	0.67
S.N.S.2	6.35	1.8	2000	350	100.5	690	0.87




**Figure 1:** Effect of pH.




**Figure 2:** Effect of Electric Conductivity.

All of the surface samples are well within the permissible limit except the samalapuram sample. Comparison of electric conductivity value of surface water sample with BIS values and of the sample of Singanallur are above the permissible limits.



**Figure 3:** Effect of TDS.



**Figure 4:** Effect of Hardness.

Comparison of the test surface water is desirable in the limit of 500mg/l and permissible with in 2000 mg/l. Samples are well within the permissible limits. Comparison of hardness values of surface water with BIS value and are exceeding the permissible limits [9,10].




Figure 5: Effect of Alkalinity.




Figure 6: Effect of Chloride.

Comparison of alkalinity values for surface water sample. The sample of sullur and singanallur are exceeding the limits. Remaining is within the permissible limits. Comparison of chloride values for surface water sample. All are the values are within the permissible limit. singanallur only having desirable value [11,12].




Figure 7: Effect of Fluoride.

Comparison of fluoride values of water sample of surface water. The samples are measured in BIS values. All samples are within the permissible limits and except sullur, singanallur, ukkadam values are desirable limit.

In the present study water samples from the four tanks namely, Coimbatore big tank, ukkadam, samalapuram and singanallur were collected all around the circumference of all the above-mentioned tanks separately. The collected samples were tested in the laboratory for various water quality parameters. The obtained water quality results show that the chloride, TDS, and hardness of most of the sample are exceeding the permissible limits [13-16].

## CONCLUSION

From the analysis of the semi-structured interview, it is clear that more than 50% of the people residing around the tanks dispose the waste from their households into the tank, which is the prime reason for water quality deterioration. Since the quality of water is being deteriorated because of anthropogenic activities, the contaminant gets transported and affects the groundwater quality. So this ground water and surface water are not absorbent for drinking purpose.

## REFERENCES

- [1] BardeAnupama, S.S. Jain and S.T Mali. International Journal of Research in Advance Technology. 2014, 2: p. 438-453.
- [2] D. Balacandar, P. Sundararaj, Rutharve1 Murthy et al., International Journal of Environmental Sciences. **2010**, (1)2: p. 176-190.
- [3] MA Jin-zhu, LAI Tian-wen, LI ji-juli, Chinese Geographical Science. **2002**, 12(1): p. 50-54.
- [4] Abdeselemakabour, Heniazedine, Chebbahlyndac et al., Procedia Engineering. **2012**, 33: p. 242-247.
- [5] S.S. Asadi, Padmaja Vuppala and M. Anji reddy. International Journal of Environmental Research and Public Health. **2007**, 4: p. 45-52
- [6] A. Pallavi Patil and S. Chaudhari Pravin. International Journal of Innovative Research Advanced Engineering. **2014**, 1: p. 188-192.
- [7] Loai Aljerf. EC Dental Science. **2017**, (1): p. 36-38.
- [8] Loai Aljerf and Nuha Al Masri. EC Dental Science. **2018**, 17(6): p. 892-899.
- [9] Maren Brehme, Traugott Scheytt, Mehmet Çelik et al., Environmental Earth Sciences. **2011**, 63(6): p. 1395-1408.
- [10] Bodrud-Doza Md., A.R.M. Towfiqul Islamb, Fahad Ahmed et al., Water Science. **2016**, 30(1): p. 19-40.
- [11] Fabíola Geovanna Piga. Multi-criteria potential groundwater contamination and human activities: Araras watershed, Brazil. RBRH 22. **2017**.
- [12] Nada Sasakova. Frontiers in Sustainable Food Systems **2018**.
- [13] SalahZereg. Sustainable Environment Research. **2018**, 28(6): p. 340-349.
- [14] Rakesh Kumar, Sudesh Yadav and Sudesh Chaudhary. Proceedings of the Indian National Science Academy, **2019**.
- [15] Ana Luiza Cunha Soares. Environmental Science and Pollution Research. **2020**, 27(12): p. 14085-14099.
- [16] Sanjay Kumar Goyal, B. S. Chaudhary, Omvir Singh et al., Environmental Earth Science. **2010**, 61: p. 1587-1597.